

1 **BURG SIMPSON ELDREDGE**
2 **HERSH & JARDINE P.C.**

3 8310 South Valley Highway, Suite 270
4 Englewood, CO 80112
5 Phone: (303) 792-5595
6 Fax: (303) 708-0527
7 Craig S. Nuss – 033839
8 Penny J. Manship – 034985
9 pmanship@burgsimpson.com

10 *Attorneys for the Plaintiff*

11 **IN THE SUPERIOR COURT OF THE STATE OF ARIZONA**
12 **IN AND FOR THE COUNTY OF MARICOPA**

13 GALLERY COMMUNITY
14 ASSOCIATION, an Arizona non-profit
15 corporation,

16 Plaintiff,

17 v.

18 K. HOVNANIAN AT GALLERY, LLC,
19 an Arizona limited liability company; et
20 al.

21 Defendants.

22 K. HOVNANIAN AT GALLERY, LLC,
23 an Arizona limited liability company; et
24 al.

25 Third-Party Plaintiffs,

26 v.

27 ARTISTIC STAIRS, LTD., an Arizona
28 limited liability company; et al.

 Third-Party Defendants.

Case No. CV2020-008714

Assigned to Hon. Michael Kemp

**PLAINTIFF’S RESPONSE TO
DEFENDANT’S SEPARATE
STATEMENT OF FACTS IN SUPPORT
FOR SUMMARY JUDGMENT**

AND

**PLAINTIFF’S CONTROVERTING
STATEMENT OF FACTS IN
OPPOSITION TO DEFENDANTS’
MOTION FOR PARTIAL SUMMARY
JUDGMENT REGARDING CLAIMS OF
UNSUPPORTED DEFECTS**

1 Plaintiff, Gallery Community Association (“Plaintiff” or “Association”), by and
2 through undersigned counsel, submits the following Response to *Defendant’s Separate*
3 *Statement of Facts in Support for [sic] Summary Judgment* (“Defendants’ SOF”) and
4 *Plaintiff’s Controverting Statement of Facts in Opposition to Defendants’ Motion for*
5 *Partial Summary Judgment Regarding Claims of Unsupported Defects* (“Assoc. SOF”).

6 **I. Plaintiff’s Response and opposition to Defendants’ Separate Statement of Facts.**

7 1. Plaintiff disclosed reports from its experts in construction liability, Ed
8 Fronapfel of SBSA, and cost of repair expert, Stefen Gustafson of Nautilus. See Exhibit A,
9 excerpts from SBSA report GALLERY-SBSA_004952 and Exhibit C, Nautilus report,
10 GALLERY-NBC_005076-5092.

11 Undisputed.

12 2. SBSA stated in its report that they identified defects in the Lateral Force
13 Resisting System (“LFRS”) and Non-Compliant Weather Resistant Barrier (WRB) for
14 Stucco System, along with recommendations for repair of those defects. See Exhibit A at
15 Gallery-SBSA_004975-4980; 005150-5151 and Gallery-SBSA_005032-5041; 005153-
16 5154.

17 Undisputed.

18 3. In support of SBSA’s claim for defects in the LFRS, SBSA points to one area,
19 located at Building D at Unit 3111, adjacent to a window, in which SBSA observed OSB
20 sheathing missing and distressed metal strap. See *Id* at Gallery-SBSA_004979-4980.

21 Undisputed.

22 4. SBSA provided photos of these defects within its report. *Id*.

23 Undisputed.

24 5. SBSA has not identified any other location with the same observed defect.
25 See Exhibit B, Deposition of E. Fronapfel at pp. 29:7-34:25.

26 It is undisputed that SBSA located only one area with missing OSB sheathing where
27 it should have been as part of the Lateral Force Resisting System (“LFRS”), and with
28 a disengaged and buckled metal strap during the intrusive examinations. SBSA

1 opined that other such locations may be discovered during the Project repairs, and to
2 the extent that these defects do exist in other locations, they should be repaired using
3 the 10% construction contingency built into the cost of repair estimate. Exh. 1B,
4 SBSA CDC Report at 29, 199-200.

5 6. Mr. Fronapfel testified that SBSA generated a set of “Observation Drawings”
6 which identify all locations where observations of conditions were made and are indexed to
7 the photographs taken by SBSA. See Exhibit B pp 29:7-34:25. E. Fronapfel testified that
8 his report does not include any index or summary of all conditions observed, but that his
9 observations of intrusive testing would be identified in his Observation Drawings. *Id* at pp.
10 45:17-47:10.

11 It is undisputed that the Observation Drawings, *together with the cross-referenced*
12 *photographs* and the SBSA CDC Report, identify and summarize all of the
13 locations where SBSA observed defects. Fronapfel Dep. 29:7-34:25, 45:17-47:10;
14 Exh. 1, Felderman Aff. ¶¶ 13, 15.

15 7. Mr. Fronapfel stated in his report that “Similar non-compliant LFRS issues
16 will more likely than not be discovered during stucco repairs recommended in Section
17 C.1.b. and C.1.c. of this report” and recommended that “[r]epair contractor to include 10-
18 percent of the stucco repair costs for use as a contingency for the repairs for the non-
19 compliance LFRS.” See *Id* at Gallery-SBSA_004980 and Gallery-SBSA_005150-5151.

20 Undisputed.

21 8. Based upon the SBSA report by Mr. Fronapfel, Mr. Gustafson, in his cost of
22 repair report, included \$200,000 for the LFRS. See Exhibit C at pp. GALLERY-
23 NBC_005078-5079. See also Exhibit D, Deposition of S. Gustafson, at pp. 59:13-62:25.

24 Undisputed.

25 9. Mr. Gustafson testified that he calculated 10% of the stucco cost and came up
26 with \$160,000, then his staff received further instructions from SBSA to round that total up
27 to \$200,000. *Id*.

28 Undisputed.

1 10. Additionally, Mr. Fronapfel claims that Non-Compliant WRB was found after
2 “[i]ntrusive examination revealed that a single layer of WRB was generally installed over
3 open stud framing and solid sheathing. Occasionally, two layers of WRB of framing were
4 identified to have been used.” See Exhibit A at GALLERY-SBSA_005032-5041.

5 Undisputed.

6 11. In support of this claim, Mr. Fronapfel cites to various codes and standards
7 that call for the use of Grade D kraft paper or equivalent water-resistive barriers, specifically
8 stating that where the application is over “wood-based sheathing,” two layers of Grade D
9 kraft paper or equivalent are required (or one layer of EPS insulation board over one layer
10 of grade D kraft paper or equivalent.) See *Id.* at GALLERY-SBSA_005033-5035, citing
11 IBC 1405.10.1.1, ESR-3529 3.1.190, ICC R703.6.3, 2510.6, 1404.2, R703.2, and ESR2376.

12 Undisputed except for the alternative WRB characterized as “(or one layer of EPS
13 insulation board over one layer of grade D kraft paper or equivalent.)” The SBSA
14 CDC Report cites ESR-352, § 3.2.10, which requires two layers of Grade D kraft
15 paper or one layer of EPS foam board “having horizontal tongue-and-groove
16 edges” over one layer of 60 minute Grade D kraft building paper. Exh. 1B, SBSA
17 CDC Report at 82.

18 12. Mr. Fronapfel’s report included photographs which appear to depict three
19 separate locations where he purports to have found areas with one layer of WRB over
20 sheathing or framing. See *Id.* at GALLERY-SSBA_005036-5041.

21 Disputed. The body of the SBSA CDC Report contains example photos depicting
22 one layer of WRB over sheathing or framing at four locations. Exh. 1B, SBSA
23 CDC Report at 85-90 (Disc IT6, Photo. 314, Bldg. A; Disc IT5, Photo. 178, Bldg.
24 B; Disc. IT5, Photo. 72, Bldg. B; Disc. IT7, Photo. 136, Bldg. D; Disc IT8, Photo.
25 114, Bldg. D).

26 13. Mr. Fronapfel further testified that areas of missing or mis-lapped WRB
27 observed by SBSA would be identified on the observation drawings. Exhibit B at pp. 63:20-
28 64:4.

1 Undisputed.

2 14. Desert Vista's expert West Harrington examined the above observation
3 drawings and produced a document highlighting and counting eleven locations where there
4 are references to observations of one or two layers of WRB over sheathing. See Exhibit E,
5 marked-up copy of SBSA Observation Drawings with highlights on SBSA references to
6 building paper, also introduced as Exhibit 130 to deposition for W. Harrington.

7 The accuracy of Mr. Harrington's analysis is disputed. See Exh. 1, Felderman Aff.
8 ¶¶ 21-22. Mr. Harrington's analysis of the locations and types of defects SBSA
9 identified is flawed because Mr. Harrington appears to have relied solely on the text
10 of the notes on the Observation Drawings, and failed to conduct a careful review,
11 which would have included examining the cross-referenced photographs in
12 conjunction with the Observation Drawings. *Id.* By doing so, Mr. Harrington failed
13 to understand all of the locations where SBSA performed intrusive examinations at
14 locations with stucco over OSB sheathing or solid wood framing (or where required
15 OSB sheathing is missing), or all such locations where only a single layer of WRB
16 was present. *Id.* The Observations Drawing and cross-referenced photographs
17 identify 26 areas where SBSA observed one or two layers of WRB over sheathing.
18 *Id.*; Exh. 1D, Observation Drawings (with Felderman highlights); Exh. 1E, cross-
19 referenced photographs.

20 15. Mr. Harrington counted fifty-four locations where references were made to
21 one or two layers of WRB over open framing or other conditions. *Id.*

22 Disputed. See response to paragraph 14.

23 16. SBSA's Observation Drawings include notes describing two layers of WRB
24 over sheathing observed by SBSA in most location, with only two notes describing
25 locations where SBA identified one layer of WRB:

- 26 a. C1.11 Front Elevation "(1) Layer OSB Shingle lapped with Rainbuster
27 Flashing / OSB Sheathing".
- 28 b. C1.16 Bldg D Rear Elevation "(1) Layer WRB above window / (2)
Layer WRB at Jamb." See Exhibit E at pages GALLERY-

1
2 Disputed.” The Observation Drawings and cross-referenced photographs identify 26
3 intrusive examinations at stucco assemblies over OBS sheathing or solid wood
4 framing where SBSA observed and documented one layer of building paper in 20
5 locations and two layers of building paper in six locations.” Exh. 1, Felderman Aff.
6 ¶ 22; Exh. 1D, Observation Drawings (with Felderman highlights); Exh. 1E, cross-
7 referenced photographs.

8 17. Nine other notes in the SBSA report note observations of WRB over
9 sheathing, and appear to reference observations of two layers of building paper. Exhibit E.

10 Disputed. See response to paragraph 16.

11 18. SBSA records indicates that areas where one layer of building paper/WRB
12 over sheathing instead of two were identified at two locations total. *Id.*

13 Disputed. See response to paragraph 16.

14 19. SBSA recommended “full removal and replacement of the stucco and the
15 exterior insulation is required to address the non-compliant installation of the WRB for the
16 existing stucco system...” See “Exhibit A” GALLERY-SBSA_005153-5154.

17 It is undisputed that paragraph 19 accurately quotes one sentence from SBSA’s
18 report. However, SBSA recommended removal and replacement of all of the
19 Project’s stucco “not because of one defect in isolation but because of the combined
20 effect of all of the identified defects,” Exh. 1, Felderman Aff. ¶ 25, described in more
21 detail below in Plaintiff’s Controverting Statement of Facts (“Plaintiff’s SSOFF”).

22 20. Mr. Stefen Gustafson of Nautilus produced reports for cost of repair for the
23 WRB conditions. See “Exhibit B” GALLERY-NBC_005076-5092 / Exhibit 59 to
24 Deposition of S. Gustafson.

25 Undisputed.

26 21. Mr. Gustafson testified that his scope of repair was to replace stucco in all
27 locations based on SBSA’s repair protocol instructing him to do so. See Exhibit C at
28 Deposition of S. Gustafson, p 43:15-43:22.

1 Undisputed.

2 22. Mr. Fronapfel has opined that the EPS foam board installed as part of the
3 stucco system contains defects. Exhibit A at GALLERY-SBSA_5042-9. He summarizes
4 his findings as “Intrusive examination revealed the foam board used at the Gallery site was
5 generally 3/8- to 7/8-inch thick, did not have the required vertical grooves, and was installed
6 tight to the improperly selected WRB.” Id. Exhibit A at GALLERY-SBSA_5042.

7 It is undisputed that SBSA opined that the EPS Foam installation was defective and
8 that the above-quoted sentence captures some of the defects in the EPS Foam
9 installation. In addition, ESR-3529 required EPS Foam with tongues and grooves
10 forming the horizontal joints as part of the building envelope, and SBSA’s intrusive
11 examinations found zero instances of tongue-and-grooved EPS Foam used. Exh. 1,
12 Felderman Aff. ¶ 19; Exh. 1B, SBSA CDC Report at 91.

13 23. Mr. Fronapfel cites to standards which state that the EPS foam boards should
14 be 1” when over open stud areas, ½” over solid surfaces, and that the EPS foam boards
15 should generally include vertical grooves. Exhibit A at GALLERY-SBSA_5042-3.

16 Undisputed except that the standards require the grooves to be “a minimum 1/4-
17 inch wide by 1/8-inch deep spaced a maximum of 12-inches to allow efficient
18 drainage of moisture between the EPS foam boards and the WRB.” Exh. 1B, SBSA
19 CDC Report at 91.

20 24. Mr. Fronapfel opined that Non-complaint EPS board exists at locations where
21 stucco is applied over solid substrates across the Gallery site” and refers to his Observation
22 Drawings and Defect Matrix for locations and findings. Exhibit A at GALLERY-
23 SBSA_5049.

24 Undisputed.

25 25. Mr. Fronapfel’s report includes 8 example photographs which he describes as
26 showing EPS board with “vertical grooves generally missing at the inner face.” Exhibit A
27 at GALLERY-SBSA_5043-9.

28 Disputed. The SBSA CDC Report contains 10 example photographs with notations

1 stating that vertical grooves were found to be missing in those locations. Exh. 1B,
2 SBSA CDC Report at 94-95, 97-98.

3 26. Mr. Harrington reviewed the Observation Drawings from Mr. Fronapfel and
4 counted three locations where Mr. Fronapfel had made reference to observation of missing
5 grooves. See Exhibit F, marked up copy of Observation Drawings with highlights regarding
6 references to EPS.

7 As described above, SBSA disputes the accuracy of Mr. Harrington's analysis.
8 Exh. 1, Felderman Aff. ¶¶ 21-22. SBSA did not find adequately sized EPS Foam
9 grooves at any of the 26 intrusive examination locations over OSB sheathing or solid
10 wood framing. *Id.* at ¶ 19.

11 27. Mr. Harrington counted in Mr. Fronapfel's observation drawings contain 40
12 references to EPS/and or foam overall. Exhibit F. Mr. Fronapfel stated in his report that
13 EPS board was observed to be "generally 3/8- to 7/8-inch thick." 222 [sic] of the 40
14 references to EPS contain Mr. Fronapfel's notes regarding observing 1" EPS. *Id.*

15 Disputed. The Observation Drawings contain 42 references to measured EPS Foam
16 thickness. Exh. 1D, Observation Drawings. Plaintiff does not dispute that 22 notes
17 reference measurements of 1" EPS Foam.

18 28. Mr. Fronapfel identified 3/8" EPS at only three locations and no other
19 locations under 1/2". *Id.*

20 Disputed. The notes on the Observation Drawings contain six references to 3/8" EPS
21 Foam. The notes contain 12 references to EPS Foam less than one inch, including
22 EPS Foam of less than 1/2 inch thickness in areas over OSB sheathing or solid wood
23 framing, and EPS Foam of less than 1 inch thickness in areas over open framing.
24 Exh. 1D, Observation Drawings (*see* notes at C1.04 – "3/8" insulation" over OSB;
25 C1.06 – "1/2" EPS" over open framing; C1.07 – "7/8" EPS" at open framing; C1.08
26 – "3/8" insulation" over OSB (Exh. 1E at p. 2, cross-referenced photo 162D, disc
27 IT5, confirms OSB); C1.08 – "3/8" insulation board" over OSB (Exh. 1E at p. 2,
28 cross-referenced photo 177D, disc IT5, confirms OSB); C1.08 – "3/8" insulation

1 board” over open framing; C1.10 – “3/8” EPS” over OSB at water shutoff opening;
2 C1.15 – “1/2” EPS on face” at open framing; C1.15 – “3/4” EPS at face” over open
3 framing; C1.16 – “3/8” EPS” over OSB; C1.16 – “7/8” EPS” over open framing;
4 C1.16 – “3/8” and 7/8” EPS”).

5 29. SBSA stated that the repair to this EPS condition was also removal and
6 replacement of the entire stucco system, and reinstallation of EPS board over solid
7 substrates. (“Full removal and replacement of the stucco and the exterior insulation is
8 required to address the non-compliant installation of the EPS foam board for the existing
9 stucco system...” Exhibit A at GALLERY-SBSA_5154.

10 It is undisputed that paragraph 29 accurately quotes one sentence from SBSA’s
11 report. However, SBSA recommended removal and replacement of all of the
12 Project’s stucco “not because of one defect in isolation but because of the combined
13 effect of all of the identified defects,” Exh. 1, Felderman Aff. ¶ 25, described in more
14 detail below in Plaintiff’s SSOF.

15 **II. Plaintiff’s Controverting Statement of Facts in Opposition to Defendants’**
16 **Motion for Partial Summary Judgment Regarding Claims of Unsupported**
17 **Defects.**

18 A. Plaintiff hired forensic engineers Charles Taylor Engineering Technical
19 Services, f/k/a SBSA, LLC a Charles Taylor Company, f/k/a SBSA, Inc. (“SBSA”) as its
20 engineering experts in this case. Exh. 1, Felderman Aff. ¶¶ 3-4.

21 B. SBSA performed a number of engineering visual examinations, intrusive
22 examinations, and analyses in this case, and generated a number of reports, including its
23 June 23, 2021, Construction and Design Compliance Report (“SBSA CDC Report”). *Id.* at
24 4; Exh. 1B, SBSA CDC Report excerpts.

25 C. As part of SBSA’s work in this case, SBSA’s team of forensic engineers spent
26 approximately 136 hours on site investigating the Gallery community’s (the “Project”)
27 condition and approximately 30 hours reviewing and analyzing the construction plans and
28 related documentation regarding how the construction was performed. Exh. 1, Felderman
Aff. ¶ 5. For all of its work on this case to date, SBSA has billed Plaintiff approximately

1 \$ 197,000. *Id.* at ¶ 6.

2 D. As is relevant to the Project's proposed stucco repairs, SBSA's forensic
3 investigation included, among other things, the following:

4 a. Visual examinations of various Project components on 9 separate days,
5 and 5 days of intrusive examinations (where an exterior element, such as
6 stucco, is removed so that otherwise hidden interior elements can be
7 examined), including, without limitation:

8 i. visual examinations of all exterior elevations at all four Project
9 buildings;

10 ii. intrusive examinations of the stucco systems at 100% of the buildings;

11 iii. approximately 44 intrusive openings into the buildings, of which
12 approximately 26 openings were made into the stucco where OSB
13 sheathing or solid wood framing was present or should have been
14 present.

15 b. Photo-documentation, including thousands of photographs documenting
16 the observed conditions, defects, and resulting damage to the Project's
17 stucco systems and adjacent building components.

18 c. Preparation of 36 pages of Observation Drawings documenting the
19 findings from the intrusive examinations, including cross-references to
20 photographs documenting the observed distress and defects.

21 d. Examination of the Project's disclosed and discovered construction plans
22 and specifications.

23 e. Review of Defendants' expert reports, including their own observations,
24 measurements, analyses, and conclusions.

25 f. Review of the relevant documentation generated during construction
26 regarding how the Project was constructed, what materials and
27 construction techniques and practices were employed, and what problems
28 were encountered.

1 g. Preparation of voluminous evaluative and repair reports correlating
2 observed defects with their locations and needed repairs.

3 *Id.* at ¶ 7.

4 E. The following construction defects and deficiencies identified in the SBSA
5 CDC Report require repairs which each separately require removal and replacement of
6 some portion of the Project's stucco systems:

- 7 a. Non-compliant Lateral Force Resisting System (LFRS)
- 8 b. Missing Weep Mechanisms in Stucco
- 9 c. Non-Compliant WRB for Stucco System
- 10 d. Non-Compliant EPS Foam Board for Stucco System
- 11 e. Non-Compliant Slope of Horizontal Stucco Surfaces
- 12 f. Deficient Self-Adhered Membrane under Horizontal Stucco System
- 13 g. Missing Control/Movement Joints in Stucco
- 14 h. Missing Sheet Metal Flashing at Fenestrations
- 15 i. Non-Compliant Flashing to Stucco Interface
- 16 j. Non-Compliant Isolation Joints at Dissimilar Materials

17 *Id.* at ¶ 8; Exh. 2, Gustafson Aff. ¶ 8.

18 F. SBSA located each of the above-listed defects requiring stucco repairs at
19 100% of the four Project buildings. Exh. 1, Felderman Aff. ¶ 9; Exh. 1C, SBSA Defect
20 Matrix (summarizing findings on a per-building basis).

21 G. In areas where the stucco assembly was placed over OSB sheathing or solid
22 wood framing, including shear walls and deck beams, the Non-Compliant Weather
23 Resistive Barrier ("WRB") for Stucco System defect consists of single-layer WRB building
24 paper rather than the necessary two layers of building paper for drainage control. In addition
25 to the lack of proper two layer asphaltic paper, the single layers were also mis-lapped. *Id.*
26 at ¶ 10.

27 H. In areas where the stucco assembly was placed over OSB sheathing or solid
28

1 wood framing, the Non-Compliant EPS Foam Board (“EPS Foam”) defect consists of
2 inadequately sized or missing vertical grooves on the back of the EPS Foam. The grooves
3 are required to allow water drainage due to the foam creating a capillary condition against
4 the asphaltic paper. In addition to the inadequate or missing grooves, the ESR report
5 installation requirements for this project required foam board with tongues and grooves that
6 create the assembly’s horizontal joints. The required minimum EPS Foam thickness was
7 also not provided. *Id.* at ¶ 11.

8 I. The photographs contained within the body of the SBSA CDC Report were
9 intended to show examples of the commonality of the Project’s conditions, and were not
10 intended to document every location where a defective condition exists. *Id.* at ¶ 12.

11 J. SBSA’s Observation Drawings, which constitute an attachment to the CDC
12 Report and were cross-referenced in the CDC Report, together with the photographs cross-
13 referenced on the Observation Drawings, document the observed locations of distress, defects,
14 and deficiencies. *Id.* at ¶ 13; Exh. 1D, Observations Drawing excerpts (with Felderman
15 highlights).

16 K. The notes on the Observation Drawings do not contain an exhaustive list of all
17 conditions observed at each location of the Project. In order to determine the conditions present
18 at each location, the Observation Drawings with associated notes must be examined in
19 conjunction with the cross-referenced photographs of each location. *Id.* at ¶ 15.

20 L. Mr. Felderman of SBSA reviewed the Observation Drawings with its
21 associated notes and cross-referenced photographs. *Id.* at ¶ 16. He highlighted the portions
22 of the Observation Drawing notes that specify intrusive examinations showing the presence
23 of OSB sheathing, solid wood framing, or missing OSB sheathing where it should have
24 been present for the LFRS. *Id.* In addition to the highlights Mr. Felderman made on the
25 Observation Drawings, the third note down on the right side of page C1.15 documents the
26 “missing OSB” at Unit 3111 discussed in SBSA’s CDC Report. *See* Exh. 1D, Observation
27 Drawings at C1.15; Exh. 1B, SBSA CDC Report at 24-29.

28 M. Where the notes on the Observation Drawings do not specify whether OSB

1 sheathing or solid wood framing was present at a particular intrusive examination cut, Mr.
2 Felderman reviewed the cross-referenced photographs and highlighted the photograph
3 numbers or photograph number ranges corresponding to the photographs which show the
4 presence of OSB sheathing or solid wood framing behind the stucco. Exh. 1, Felderman
5 Aff. ¶ 16; *see also* Exh. 1E, photographs documenting presence of OSB and solid wood
6 framing. Each highlighted section of text or photograph numbers corresponds to one
7 intrusive examination cut where SBSA found OSB sheathing or solid wood framing. *Id.*

8 N. SBSA made approximately 26 intrusive examination cuts over OSB sheathing
9 or solid wood framing, or in an area where OSB sheathing was required but missing. Exh. 1,
10 Felderman Aff. ¶ 17.

11 O. In 100% of these locations, SBSA observed one or more of the following:
12 missing vertical grooves on the back of the EPS Foam, missing tongues and grooves in the
13 EPS Foam for horizontal joints, inadequate EPS Foam thickness, single-layer WRB
14 building paper, and/or mis-lapped WRB building paper. *Id.* at ¶ 18.

15 P. In all of its intrusive examinations of the Project, SBSA found zero locations
16 with adequately profiled grooved EPS Foam and zero locations with tongues and grooves
17 in the EPS Foam. *Id.* at ¶ 19.

18 Q. In addition, in 100% of the locations where SBSA visually examined the
19 stucco assemblies without intrusive examinations, SBSA observed non-compliant slope at
20 horizontal surfaces, missing weep mechanisms at horizontal terminations, missing control
21 joints, missing sheet metal flashings at fenestrations, non-compliant flashing to stucco
22 interface, and/or non-compliant isolation joints at dissimilar materials. *Id.* at ¶ 20.

23 R. Mr. Felderman reviewed *Defendant's Separate Statement of Facts in Support*
24 *for [sic] Summary Judgment*. *Id.* at ¶ 21. He has opined that Mr. Harrington's analysis of
25 the locations and types of defects SBSA identified is flawed because Mr. Harrington
26 appears to have relied solely on the text of the notes on the Observation Drawings, and
27 failed to conduct a careful review, which would have included examining the cross-
28 referenced photographs in conjunction with the Observation Drawings. *Id.* Mr. Felderman

1 opined that by doing so, Mr. Harrington failed to understand all of the locations where
2 SBSA performed intrusive examinations at locations with stucco over OSB sheathing or
3 solid wood framing (or where required OSB sheathing is missing), or all such locations
4 where only a single layer of WRB was present. *Id.* Thus, Mr. Felderman opined that “Mr.
5 Harrington’s non-rigorous review of the CDC Report, its attachments, and cross-referenced
6 photographs and findings have lead him to an incorrect conclusion.” *Id.*

7 S. For example, Mr. Harrington incorrectly concluded that the Observation
8 Drawings reference nine instances of two layers of building paper over OSB sheathing and
9 two instances of one layer of building paper over sheathing. *Id.* at ¶ 22. Instead, Mr.
10 Felderman determined that the Observation Drawings and cross-referenced photographs
11 when examined together identify 26 intrusive examinations at stucco assemblies over OBS
12 sheathing or solid wood framing where SBSA observed and documented one layer of
13 building paper in 20 locations and two layers of building paper in six locations. *Id.* And in
14 those six locations with two layers of building paper, other defects and deficiencies were
15 present, requiring removal and replacement of portions of the stucco assemblies to perform
16 repairs. *Id.*

17 T. Based on his experience and expertise in the examination of the built
18 environment on hundreds of projects, Mr. Felderman opined that “because SBSA found
19 conditions requiring removal and replacement of portions of the stucco at 100% of the areas
20 where SBSA performed intrusive examinations over OBS sheathing or solid wood framing
21 at various locations over the expanse of all four Project buildings, these same defective
22 conditions are, to a reasonable degree of engineering probability, likely to exist throughout
23 other areas of the Project not subject to intrusive examination.” *Id.* at ¶ 23.

24 U. “This is true in part because the stucco assembly is constructed with rolls of
25 asphalt paper, sheets of foam, and rolls of lathe, and correctly applying them requires
26 consideration of the layout from bottom to top on each building elevation to create a
27 properly lapped system. Based on finding an improperly lapped system in one or more
28 areas, the means and methods of construction, the products used, and their assembled state

1 in other locations on the same building can be inferred.” *Id.* at ¶ 24.

2 V. SBSA recommended removal and replacement of all of the Project’s stucco
3 not because of one defect in isolation but because the combined effect of all of the identified
4 defects would result, at best, in a patchwork of small stucco locations where repairs are not
5 required. *Id.* at ¶ 25.

6 W. Mr. Felderman further opined that based on his “experience and expertise,
7 because of the significant quantity of stucco areas requiring removal and replacement, it
8 would not be practical, reasonable, or efficient to attempt to remove and replace only the
9 large areas of stucco where repairs must be performed.” *Id.* at ¶ 25.

10 X. Mr. Felderman also confirmed that SBSA’s above-described investigation,
11 reports, and data comprise information of a type reasonably relied on by other forensic
12 engineers in forming opinions like those SBSA has formed in this case relating to damages,
13 defects, and deficiencies at the Project and the scope of reasonable and necessary repairs.”
14 *Id.* at ¶ 26.

15 Y. Plaintiff hired Nautilus Contractors, Inc. to perform destructive testing and
16 reconstruction during the discovery phase of this case as directed by SBSA. Exh. 2,
17 Gustafson Aff. ¶ 1. Plaintiff hired Nautilus Consultants (“Nautilus”) to perform a cost of
18 repair estimate for the scope of Project repairs specified by SBSA. *Id.*

19 Z. Stefan Gustafson of Nautilus has 38 years of experience in the construction
20 industry. He attested that the defect repairs “require removal and replacement of specific
21 portions of the stucco on every exterior wall plane on the Project in order to repair or
22 integrate the underlying or adjacent conditions.” *Id.* at ¶ 9.

23 AA. Mr. Gustafson used an elevation drawing of a typical Project building
24 provided to him by SBSA, with locations where OSB sheathing is present beneath the
25 stucco marked as red shading, to illustrate the large areas of stucco that the prescribed
26 repairs would require him to remove. *Id.* at ¶ 7; Exh. 2B, Repair Drawing.

27 BB. He then highlighted in pink the additional areas of stucco, outside the OSB
28 sheathing areas, that must be removed and replaced to repair or integrate the underlying or

1 adjacent conditions because of the following defects: non-compliant cross slope of
2 sidewalks (requiring new stair landing heights), missing weep mechanisms in stucco, non-
3 compliant slope of horizontal stucco surfaces, deficient self-adhered membrane under
4 horizontal stucco system, missing control joints, missing sheet metal flashing at window
5 heads, non-compliant flashing to stucco interface, and non-compliant isolation joints at
6 dissimilar materials. Exh. 2, Gustafson Aff. ¶¶ 8-9.

7 CC. Neither Plaintiff nor its experts concede that the red shaded and pink
8 highlighted areas marked on Exhibit 2B constitute all of the areas where SBSA identified
9 defects beneath the stucco. For purposes of this analysis only, Mr. Gustafson has been asked
10 to assume that “the *WRB and EPS Foam deficiencies* require removal and replacement of
11 stucco only in locations where OSB sheathing, or other solid substrates, such as wood
12 framing, are present beneath the stucco.” Exh. 2, Gustafson Aff. ¶ 7 (emphasis added).
13 These areas are represented by the red shading on Exhibit 2B. *Id.* The additional pink
14 shading represents where stucco repairs are required because of *other defects*. *Id.* at ¶¶ 8-9.

15 DD. In each location where stucco must be removed and replaced in order to repair
16 adjacent or underlying conditions, the removal results in the destruction of the underlying
17 WRB and EPS Foam board, which must also be removed and replaced. *Id.* at ¶ 10.

18 EE. If the stucco were to be removed and replaced only in the locations marked
19 with shading and highlighting on Exhibit 2B, a section of stucco approximately 12-18
20 inches wide around each repair must be removed and replaced in order to accommodate the
21 repair and re-integrate the new underlying WRB building paper and EPS Foam with the
22 existing building paper and EPS Foam beneath adjacent stucco areas. *Id.* at ¶ 11.

23 FF. The amount of stucco required to be removed and replaced due to the WRB
24 and EPS Foam deficiencies at the areas over OSB sheathing (marked in red shading on
25 Exhibit 2B), together with the extensive amount of additional stucco removal and
26 replacement required in areas outside the OSB sheathing areas *because of other defects*
27 (highlighted in pink on Exhibit 2B) would leave only small, discrete areas of original stucco
28 remaining in place. *Id.* at ¶ 12.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

GG. Mr. Gustafson opined that in his professional experience, it would not be practical, reasonable, or efficient to leave only these patches of stucco in place while implementing the prescribed repairs. *Id.* at ¶ 13. In addition to re-integrating the new WRB building paper and EPS Foam with the existing WRB and EPS Foam under adjacent stucco areas, the patchwork stucco repair approach would require the repair contractor to texture coat and paint the entire wall plane on each wall to match the existing stucco patches to the newly-replaced stucco. *Id.*

HH. From a constructability perspective, patching in the numerous pre-existing stucco areas with the areas needing stucco repairs (marked in shading and highlighting on Exhibit 2B) would be labor intensive, time consuming, expensive, and less efficient than simply removing all of the stucco in one effort, and making all of the stucco repairs together. *Id.* at ¶ 14.

II. Mr. Gustafson also opined that in his professional experience, he does “not believe that any experienced and reasonably prudent contractor would be willing to warrant the stucco repairs in the absence of completely removing and replacing the stucco system, given the volume of areas needing repairs and the amount of patching and integrating into the existing systems that a patchwork approach would require. *Id.* at ¶ 15.

JJ. It is undisputed that the same subcontractor, Third-Party Defendant Desert Vista, Inc., (“Desert Vista”) performed all of the Project’s original stucco construction, including the WRB and EPS Foam installation. Exh. 3, Desert Vista 30(b)(6) (Jones) Dep. 38:6-40:8, 69:21-73:4, 74:15-75:1 (discussing Desert Vista’s scope of work).

1 Respectfully submitted,

2 BURG | SIMPSON | ELDREDGE | HERSH | JARDINE PC

3 By: /s/ Penny J. Manship
4 Craig S. Nuss, Esq.
5 Penny J. Manship, Esq.
6 Grace M. Osberg, Esq.
7 8310 South Valley Highway, Suite 270
8 Englewood, CO 80112
9 (303) 792-5595
10 (303) 708-0527 (fax)
11 cnuss@burgsimpson.com
12 pmanship@burgsimpson.com
13 gosberg@burgsimpson.com

14 *Attorneys for the Plaintiff Gallery Community Association*

15 The foregoing E-FILED via AZTurboCourt
16 Electronic filing system and E-MAILED this
17 7th day of November, 2022 to:

18 Dennis I. Wilenchik, Esq.
19 Heather Zwick
20 Barbara Stansil
21 Wilenchik & Bartness, P.C.
22 2810 North Third Street
23 Phoenix, AZ 85004
24 admin@wb-law.com
25 diw@wb-law.com
26 heatherz@wb-law.com
27 barbaras@wb-law.com

28 *Attorneys for Defendants/ThirdParty Plaintiffs K. Hovnanian at Gallery, LLC; K.
Hovnanian Arizona Operations, LLC; K. Hovnanian Developments of Arizona, Inc.; K.
Hovnanian Companies of Arizona, LLC*

29 Teresa Hayashi Wales
30 WELSH LAW GROUP, PLC
31 11811 North Tatum Boulevard, Suite P125 Phoenix, AZ 85028
32 minuteentries@welshlawgroup.com
33 twales@welshlawgroup.com
34 *Attorneys for Chas Roberts Air Conditioning, Inc.*

1 Leonard T. Fink, Esq.
2 David S. Schopick, Esq.
3 SPRINGEL & FINK LLP
4 3033 North Central Ave., Suite 500
5 Phoenix, AZ 85012
6 lfink@springelfink.com
7 dschopick@springelfink.com
8 *Attorneys for Third-Party Defendant, SARGON MASONRY CONSTRUCTION, LLC*

9 C. Cole Crabtree
10 Amanda R. Hough
11 Jaburg & Wilk, P.C.
12 3200 N. Central Avenue, 20th Floor
13 Phoenix, AZ 85012
14 ccc@jaburgwilk.com
15 aah@jaburgwilk.com
16 *Attorneys for Third-Party Defendant Gothic Landscaping, Inc.*

17 Michael A. Ludwig, Bar #015481
18 Stephen F. Best, Bar #034976
19 JONES, SKELTON & HOCHULI, P.L.C.
20 40 North Central Avenue, Suite 2700
21 Phoenix, Arizona 85004
22 minuteentries@jshfirm.com
23 mludwig@jshfirm.com
24 sbest@jshfirm.com
25 *Attorneys for Third-Party Defendant LeBlanc*
26 *Building Co., Inc.*

27 Tom Shorall Jr., #010456
28 Jason J. Boblick, #026507
Shorall McGoldrick Brinkmann
1232 East Missouri Avenue
Phoenix, AZ 85014-2912
tomshorall@smbattorneys.com
jasonboblick@smbattorneys.com
smb@smbattorneys.com
Attorneys for Third Party Defendant
Liberty Constructors

/s/ Laura M. Ramirez

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28