

# EXHIBIT 2

BSC File No. 220080S

JSH File No. 17412-00067



Typical view of destructive investigation work through the stucco cladding and foam insulation at roof parapet.



Typical view of crack in stucco.

# EXHIBIT 2

BSC File No. 220080S

JSH File No. 17412-00067



Typical view of cracks in stucco.



Typical view of cracks in stucco.

# EXHIBIT 2


BSC File No. 220080S

JSH File No. 17412-00067

## Exterior Wood Framing Photographs



View of exterior wood panels behind deconstructed stucco cladding and building paper.



View of exterior wood panels and metal straps behind deconstructed stucco cladding and building paper.

# EXHIBIT 2

BSC File No. 220080S

JSH File No. 17412-00067



View of exterior wood panels and metal straps behind deconstructed stucco cladding and building paper.



View of typical wood framing near balcony.

# EXHIBIT 2

## Roofing Photographs



View of rooflines of typical buildings.



View of typical roof condition and slope.

# EXHIBIT 2

BSC File No. 220080S

JSH File No. 17412-00067



View of typical roof condition and slope.



View of typical roof condition and slope.

# EXHIBIT 2

BSC File No. 220080S

JSH File No. 17412-00067



View of typical roof condition and slope.



View of crack/tear in roof surface.

# EXHIBIT 2


BSC File No. 220080S

JSH File No. 17412-00067



View of flashing termination at location of tear in roof depicted in previous photograph.

## Interior Photographs



View of room with ceiling stain and crack below location of tear in roofing depicted in previous photograph.

# EXHIBIT 2

BSC File No. 220080S

JSH File No. 17412-00067



View of ceiling stain and crack below general location of tear in roofing depicted in previous photograph.