

## View Inspection

<a href="#">Quick Search</a>
<a href="#">Swimming Pools Home</a>

Permit ID	Inspection Date	Inspection Type
SP-10363	07/02/2020	Routine Inspection

  

Violation ID	Violation Description	Violation Comments	Correct By
1A Chapt.6 Sec3 R1b,c	Pool interior surface cracked, not smooth and easily cleanable and/or slip resistant where needed.	Repair pool surface to be smooth, easily cleanable and durable. Areas in bathing places that are intended to provide footing shall have a slip resistant surface. Interior surface has minor pitting/chipping. Repair.	Correct Prior To Next Routine Inspection

  

Inspection Comments
No County legal action will result from this inspection. Report emailed to operator.



Environmental Services Dept.  
501 N. 44th Street Suite #200  
Phoenix, AZ 85008  
Phone: [602-506-6616](tel:602-506-6616)